



	Canyon#	Part Name	Qty.
1	A1022941	sleeve	1PC
2	A1022942	spacer	2PCS
4	A1022943	screw	1PC
5	A1016890	linkage shock nut	3PCS
6	A1000736	bearing 6902-2RS	2PCS
7	A1013166	retaining ring	1PC
8	A1012197	Hammerschmidt plate	1PC
9	A1016707	E-Type plate E59-10	1PC
11	A1013172	shock mount screw	1PC
12	A1012680	Torque FR Swing	1PC
14	A1017954	E-type nut	1PC
15	A1012889	screw	1PC
16	A1012028	bearing 608-2RS	4PCS
18	A1013175	spacer	2PCS
19	A1022944	sleeve	1PC
20	A1013178	screw	4PCS
21	A1013184	spacer	4PCS
24	A1013179	nut	2PCS
25	A1013180	spacer	4PCS
26	A1013185	joint screw	2PCS
27	A1013186	joint axis	2PCS
28	A1022945	washer	2PCS
29	A1013187	bearing 698-2RS	4PCS
30	A1001666	RD-Hanger #12	1PC
		incl. screws	2PCS
32	A1013164	dust cap	1PC
33	A1012196	screws for Hammerschmidt plate	3PCS
34	A1017953	screws for E-type plate	2PCS
35	A1005111	satellite with bolt	11Sets
36	A1017499	Canyon bushing E60-II	4PCS
37	A1014819	protection foil	1PC
38	A1004922	FSA No.55-3 Canyon 1 1/8-1 1/2" tapered	1Set
	A1004921	FSA No.55-2 Canyon 1 1/8"	1Set
39	A1005069	Rock Shox Monarch 4.2 HighVolume, D-Tune	222x66 1PC
	A1005049	Answer Manitou Evolver ISX-6	222x70 1PC
40	see drawing	Seat Clamp 31.6/36mm	1Set

rear triangle should fall by itself after assembly!

TORQUE ES | M18-09

